



# AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple listee model(s) identified on the correlation page of the Listing Report.

This document is the property of Intertek Testing Services and is not transferable. The certification mark(s) may be applied only at the location of the Party Authorized To Apply Mark.

**Applicant:** Oseco  
**Address:** 1701 West Tacoma  
Broken Arrow, OK 74012  
**Country:** USA  
**Contact:** Mr. Robert Jackson  
**Phone:** (918) 259-7129  
**FAX:** (918) 251-7662  
**Email:** rjackson@oseco.com

**Manufacturer:** Oseco  
**Address:** 1701 West Tacoma  
Broken Arrow, OK 74012  
**Country:** USA  
**Contact:** Mr. Robert Jackson  
**Phone:** (918) 259-7129  
**FAX:** (918) 251-7662  
**Email:** rjackson@oseco.com

**Party Authorized To Apply Mark:** Same as Manufacturer  
**Report Issuing Office:** CRT

**Control Number:** 4005104

**Authorized by:** *Patricia Jones*  
William T. Starr, Certification Manager



This document supersedes all previous Authorizations to Mark for the noted Report Number.

This Authorization to Mark is for the exclusive use of Intertek's Client and is provided pursuant to the Certification agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Authorization to Mark. Only the Client is authorized to permit copying or distribution of this Authorization to Mark and then only in its entirety. Use of Intertek's Certification mark is restricted to the conditions laid out in the agreement and in this Authorization to Mark. Any further use of the Intertek name for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. Initial Factory Assessments and Follow up Services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purposes of production quality control and do not relieve the Client of their obligations in this respect.

Intertek Testing Services NA Inc.  
165 Main Street, Cortland, NY 13045  
Telephone 800-345-3851 or 607-753-6711 Fax 607-756-6699

**Standard(s):**

- Intrinsically Safe and Non-Incendive Equipment for Use in Hazardous Locations; Consumer and Commercial Products; General Instruction No 1: 1992/06/01- (R2006), Issue:1992/01/01 Ed:3 (CSA C22.2 No. 157)
- UL Standard for Safety Intrinsically Safe Apparatus and Associated Apparatus for Use in Class I, II, and III, Division I, Hazardous (Classified) Locations, Issue:2006/07/31 Ed:7 Rev: 2011/09/23 (UL 913)
- Non-Incendive Electrical Equipment for Use in Class I, Division 2 Hazardous Locations; General Instruction No 1: 1987/03/01 - (R2008), Issue:1987/03/01 Ed:1 (CSA C22.2 No. 213)
- Nonincendive Electrical Equipment for Use in Class I and II, Division 2 and Class III, Divisions 1 and 2 Hazardous (Classified) Locations, Issue:2011/24/August (ISA 12.12.01)



# AUTHORIZATION TO MARK

<b>Product:</b>	Rupture Disk Sensor Class I, Division 1 & 2, Group ABCD, T2D Ambient: -50F to +400F Entity Parameters: I <sub>max</sub> =150mA, V <sub>max</sub> =25.5V, C <sub>i</sub> =0.0036μF, L <sub>i</sub> =12μH Control Drawing: EXX-XXXX-XXXX9-CD
<b>Models:</b>	AMS, CMS



165 Main Street  
Cortland, NY 13045

Telephone: 607-753-6711  
Facsimile: 607-756-6699  
www.intertek-etlsemko.com

**ETL FOLLOW-UP SERVICE  
INSPECTION REPORT**

Internal Use Only  
 Project # \_\_\_\_\_  
 Customer # \_\_\_\_\_  
 Stream # \_\_\_\_\_  
 Invoice # \_\_\_\_\_

Manufacturer OSECO

Page 2 of 2

Listing Report No. 10050566ACRT-001 Issue/Rev. Date 2-23-12

Date 22 / 03 / 12  
 Day Month Year

Product Rupture Disk Sensor

1 Qtr  2 Qtr  3 Qtr  4 Qtr  Other IFA

Intertek Representative Jack Welker

Order No. 4005104

Page	Item	Complies	Comment
2-4	1-5	OK	Photo Matches
5-6	1-4	✓	
7-10	All	✓	
11-12	All	✓	
13-14	All	-	Test Data
15-17	All	✓	

**ETL FOLLOW-UP SERVICE  
INSPECTION REPORT**

Manufacturer OSECO

Page 1 of 2

Factory Address 1701 West Tacoma  
Broken Arrow, OK 74012

Date 

22	03	12
Day	Month	Year

1 Qtr  2 Qtr  3 Qtr  4 Qtr  IPI/IFA  Other

Intertek Representative Jack Welker

Order No. 4005104

**Directions to Intertek Representative:** Verify that products comply with all items specified in the Listing Report/CDR and that production line tests and procedures specified are being conducted. All variations should be noted on this report and conveyed by phone/fax/email to the Manager of Follow-up Service.

**The following items were reviewed with the manufacturer:**

- a. Is use of listing label controlled? Yes  No  N/A
- b. Labeling Method:  
 Separable Labels (supplied by Intertek)  
 Direct Imprint (by Client)  
 Both
- c. Are product markings per Listing Report? Yes  No
- d. Is production line testing required? Yes  No   
If Yes 1) Is testing being performed Yes  No   
as required?  
2) Is equipment calibrated? Yes  No
- e. Qty of ETL labelled product shipped since last inspection 0
- f. Changes, additions, options, or accessories, etc. were made to Listed Products. Yes  No
- g. Have changes occurred to the manufacturing process or quality system that affects Listed Products? Yes  No
- h. Were variations noted on the last inspection? Yes  No   
If yes, has the client responded? Yes  No   
Have all variations been resolved? Yes  No   
If no, provide details on F2  
Has report been corrected? Yes  No  N/A
- i. Has the procedure or records for customer complaints/field failures been reviewed? Yes  No

Letter of Explanation is required from the client for these non-compliant item numbers \_\_\_\_\_

Send Variation Response Letter with a copy of this Inspection Report to Intertek, Cortland, NY, by mail, fax, or email [VariationResponse.Cortland@intertek.com](mailto:VariationResponse.Cortland@intertek.com).

\_\_\_\_ Variations accepted per phone/fax communication with \_\_\_\_\_

\_\_\_\_ Variations NOT accepted per phone/fax communication with \_\_\_\_\_

\_\_\_\_ Labels removed by mfr. \_\_\_\_\_ Product held \_\_\_\_\_ Inspector's time in factory \_\_\_\_\_ Hrs.

*Arrive 10:00  
Depart 11:45*

I acknowledge receipt of a copy of this inspection report issued by Intertek Testing Services NA Inc.

Robert Jackson 3/22/12  
Factory Representative's Signature Date

Robert Jackson

Factory Representative's (printed name)

Jack Welker  
Intertek Representative's Signature

Continued on next page  
Form F1 May 1, 2010



**Intertek**

This report is for the exclusive use of Intertek's Client and is provided pursuant to the Certification Agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the inspected/tested material, product or service must first be approved in writing by Intertek. This report by itself does not demonstrate that the material, product, or service is, or has ever been, eligible to bear an Intertek certification mark. Initial Factory Assessments and Follow up Services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purposes of production quality control and do not relieve the Client of their obligations in this respect.